







June 28th 2023 Revision

Installation Advisory IA E-04.6

Affects: Model E-04 Audio Alert battery Model E-04C Remote Control

Because of the many quality control problems, we have seen recently with Duracell CR 2 batteries leaking <u>we no longer recommend</u> using Duracell batteries in the Audio Alert (P/N E-04.7) or the E-04C Remote (P/N E-05.1)

Battery leakage in the Audio Alert can cause inadvertent activation of the ELT, or constant dim blinking of the remote LED which will cause the remote battery to discharge.

Following is a list of recommended Lithium batteries for the E-04 Audio Alert and the E-04C Remote. These have a 10 year replacement interval. The use of other manufacturers equivalent batteries is acceptable.

ManufacturerPart numberPanasonicCR2EnergizerCR2VartaCR2

Duracell warrantees their battery's and will repair or replace devices damaged by leakage of their batteries.

## DURACELL BATTERY GUARANTEE

GUARANTEE: If not completely satisfied with your Duracell battery product, call 1-800-551-2355 (9:00AM – 5:00PM EST). Duracell guarantees its batteries against defects in materials and workmanship. Should any device be damaged due to a battery defect, we will repair or replace it at our option. Leaking battery and damaged device must be provided as proof of claim. Duracell may deny claims of damage caused by misuse or modification of the batteries or device.

CAUTION: May explode or leak, and caused burn injury, if recharged, disposed of in fire, mixed with different battery type, inserted backwards or disassembled. Replace all used batteries at the same time. Keep in original package until ready to use. Do not carry batteries loose in your pocket or purse. Do not remove the battery label.

BEST BEFORE: See Date on Battery or Package.

DURACELL